

Release Notes



IMPORTANT: The AT-OME-EX-KIT-LT should be updated as a kit, and the TX and RX should be connected via their HDBaseT connectors prior to the firmware update.



IMPORTANT: The firmware is applied to both the MCU and Valens chipset. Since both chips are being updated, the update process can take anywhere from 5 to 10 minutes. Do not power off the system until the firmware update process is complete.

Public Release

Version 1.2.4	
Features	None.
Bug Fixes	- Updated to Valens Firmware 7.5.21. - Resolved compatibility issue with products such as ClearOne Versa Mediabar™ Video Soundbar. Poly Studio P15 and R30, Yealink, etc. - General USB improvements.
Known Issues	None

Previous Releases

Version 1.2.3	
Features	Support for revision B and newer hardware.
Bug Fixes	None
Known Issues	None

Version 1.2.2	
Features	None
Bug Fixes	- Update to Valens Firmware 7.5.4. - Resolved an issue where cascading of HDBaseT extenders would cause degradation in both USB audio and video quality.
Known Issues	None

Version 1.1.03	
	Factory firmware