

Release Notes



IMPORTANT: The firmware is applied to both the MCU and Valens chipset. Since both chips are being updated, the update process can take anywhere from 5 to 10 minutes. Do not power off the system until the firmware update process is complete.

Public Release

Version 1.2.4	
Features	Added support for AT-OME-MS42-HDBT firmware 1.0.0.
Bug Fixes	- Updated to Valens Firmware 7.5.21. - Resolved compatibility issue with products such as ClearOne Versa Mediabar™ Video Soundbar. Poly Studio P15 and R30, Yealink, etc. - General USB improvements.
Known Issues	None

Previous Releases

Version 1.2.2	
Features	None
Bug Fixes	- Update to Valens Firmware 7.5.4. - Resolved an issue where cascading USB connections over HDBaseT would cause USB to fail. - Fixed a USB-C compatibility issue where no image would be displayed when connect to the system. Resolved compatibility issues with the following devices: » HP EliteBook » HP Chromebook 360 » Fujitsu Lifebook
Known Issues	None

Version 1.2.1	
	Factory firmware