

Release Notes



IMPORTANT: The firmware is applied to both the MCU and Valens chipset. Since both chips are being updated, the update process can take anywhere from 5 to 10 minutes. Do not power off the system until the firmware update process is complete.

Public Release

Version 1.2.4	
Features	- Added support for AT-OME-MS42-HDBT firmware 1.0.0. - Updated AT-OME-EX-RX HDMI OUT 5V default behavior to follow presence of video source. - Added OutHdmi5vFollow [local remote sta] command. Use this command to set the behavior of the AT-OME-EX-RX HDMI 5V. Refer to the AT-OME-EX-RX manual for more information.
Bug Fixes	- Updated to Valens Firmware 7.5.21. - Resolved compatibility issue with products such as ClearOne Versa Mediabar™ Video Soundbar. Poly Studio P15 and R30, Yealink, etc. - General USB improvements.
Known Issues	None

Previous Releases

Version 1.2.2	
Features	None
Bug Fixes	- Update to Valens Firmware 7.5.4. - Resolved an issue where cascading of HDBaseT extenders would cause degradation in both USB audio and video quality.
Known Issues	None

Version 1.2.1	
Features	- AT-OME-EX-TX: Support for hardware revision C. Adds control for powering on/off of the USB hub. When no PC is connected, the USB hub turns off. When a PC is connected, the USB hub turns on. - AT-OME-EX-RX: Support for hardware version D. Firmware 1.2.1 is <i>not</i> required for USB hub power control.
Bug Fixes	None
Known Issues	None

Version 1.1.03	
Features	None
Bug Fixes	- Improved USB performance. - The USB HUB 5V signal is no longer held high on the receiver, when no USB HOST is present.
Known Issues	None

Release Notes

Version 1.1.0

Features	• None
Bug Fixes	• Improved support for USB cameras, specifically Lumens. • Resolved an issue where RS-232 would only function at a baud rate of 115200.
Known Issues	• None

Version 1.0.06

Features	• Added compatibility with the AT-OME-PS62.
Bug Fixes	• None
Known Issues	• None

Version 1

- Factory firmware