

Release Notes



IMPORTANT: The AT-USB-EX100-KIT should be updated as a kit, and the TX and RX should be connected via their HDBaseT connectors prior to the firmware update.



IMPORTANT: The firmware is applied to both the MCU and Valens chipset. Since both chips are being updated, the update process can take anywhere from 5 to 10 minutes. Do not power off the system until the firmware update process is complete.

Public Release

Version 1.0.3	
Features	The maximum number of allowed (physical) USB hubs supported in the system increased from 6 to 9.
Bug Fixes	- Updated to Valens Firmware 2.200.17. - Resolved compatibility issue with ClearOne Versa Mediabar™ Video Soundbar. - Resolved compatibility issue with Poly Studio P15 and R30.
Known Issues	None

Previous Releases

Version 1.0.2	
Features	Added support for applications that require VID and PID detection (for example, Logitech Sync).
Bug Fixes	- Updated to Valens Firmware 2.200.9. - Resolved an issue where USB device enumeration is not reliable when those devices are connected to the AT-USB-EX100-KIT via two HDBase-T extenders (as opposed to being directly connected to the AT-USB-EX100-KIT).
Known Issues	None

Version 1.0.1	
Features	- Added support for revision C and newer hardware. - Improved overall bandwidth performance from 280 Mbps to 315 Mbps.
Bug Fixes	- Fixed issue where after a power cycle of Logitech Pro PTZ 2, the USB host will no longer enumerate the camera. - Update to Valens Firmware 1.201.9.
Known Issues	None

Version 1.0.0	
	Factory firmware