

Release Notes



IMPORTANT: The AT-OME-EX-WP-KIT-LT should be updated as a kit, and the TX and RX should be connected via their HDBaseT connectors prior to the firmware update.



IMPORTANT: The firmware is applied to both the MCU and Valens chipset. Since both chips are being updated, the update process can take anywhere from 5 to 10 minutes. Do not power off the system until the firmware update process is complete.

Public Release

Version 1.2.4.1	
Features	• None.
Bug Fixes	• Updated to Valens Firmware 7.5.21. • Resolved compatibility issue with products such as ClearOne Versa Mediabar™ Video Soundbar. Poly Studio P15 and R30, Yealink, etc. • General USB improvements.
Known Issues	• When updating to 1.2.4.1 from a previous version, the update procedure must be run twice.

Previous Releases

Version 1.2.2	
	• Factory firmware